

Copyright is owned by the Author of the thesis. Permission is given for a copy to be downloaded by an individual for the purpose of research and private study only. The thesis may not be reproduced elsewhere without the permission of the Author.

Emergency Management Response to Landslide Dams following the 2016 Kaikoura Earthquake

A thesis presented in partial fulfilment of the
requirement for the degree of

Masters
in
Emergency Management

at Massey University, Wellington,
New Zealand

Lucinda Emily Marlene Swatton



MASSEY
UNIVERSITY

March 2018

Abstract

This research examines the response and emergency management of the Kaikoura earthquake landslide dams formed on the 14th November 2016 by a M 7.8 earthquake which caused extensive damage across Hurunui, Kaikoura and Marlborough. The Kaikoura earthquake caused tens of thousands of landslides and over 200 of those generated dams that blocked rivers. The widespread damage and number of landslide dams was unusual and required a significant response. This involved many agencies and organisations undertaking different aspects of the response.

Following the Kaikoura event, the scientific community responded, identifying the dams before carrying out risk assessments of those dams posing a threat to people and infrastructure. As the scale of the event was discovered the response involved other agencies such as district and regional councils, transport agencies, Civil Defence and Emergency Management and geotechnical consultants.

To evaluate the emergency response and management of the dams, semi structured interviews were carried out with 18 personnel from ten different agencies and organisations involved in the response. The interviews covered seven topic areas which were developed through the literature and news article review. Analysis of the interview data using content analysis involved transcribing each interview before sorting and coding the transcripts.

The analysis highlighted nine main themes. These are: roles and responsibilities; communication; co-ordination; resources; previous experience; community involvement; information and data; relationships; and long-term management. A review and discussion of those themes emphasised the need for improvements in preparedness for future events.

The recommendations developed from the analysis are: clarification of responsibilities; planning of response procedures; hazard modelling; creation of a panel agreement for work-sharing; development of geographic sectors; workshops; training; public communication; resources; development of a database; and information sharing.

The learnings from Kaikoura can be used to improve future responses for both landslide dams and multi-hazard events across large geographical areas. It is predicted that an earthquake generated by the Alpine Fault could cause severe land damage across a vast geographical area. The Kaikoura earthquake has highlighted the need to focus on landslide dams as a significant hazard to communities, infrastructure and transport links.

Acknowledgements

Firstly, I would like to thank both of my supervisors, Professor David Johnston and Dr Julia Becker for their support, positive encouragement and guidance throughout this research.

I would like to thank all those who participated in my interviews. All of the interviewees were very generous with their time and knowledge. Their input into this research was invaluable and I am very grateful for their contribution.

Thank you to my partner Erwin, your support and patience helping me through this thesis was greatly appreciated.

Lastly, I would like to thank my family and friends for all their love and support. I am especially grateful to my parents who have supported me through this research and have been there for anything I needed. I could not have completed this thesis without you being there constantly encouraging me along the way.

Table of Contents

Abstract	ii
Acknowledgements	iii
Table of Contents	iv
List of Figures	viii
List of Tables	x
Chapter 1 - Introduction	1
1.1 Context.....	1
1.2 Research Objectives.....	2
1.3 Research Methodology.....	3
1.4 The Kaikoura Earthquake Sequence (Background).....	4
1.4.1 Geological Context of Region.....	7
1.4.2 Earthquake Induced Land Damage Impacts.....	8
1.5 Landslide Dams Overview.....	15
1.6 Thesis Outline.....	18
Chapter 2 - Research Methodology	20
2.1 Introduction.....	20
2.2 Literature Review.....	21
2.3 Kaikoura Landslide Dams Interviews.....	22
2.3.1 Interviewee Selection.....	23
2.3.2 Interview Questions.....	24
2.3.3 Ethics Approval.....	25
2.3.4 Data Collection.....	25
2.4 Interview Data Analysis.....	27
2.4.1 Transcription.....	28
2.4.2 Data Coding.....	28
2.5 Results interpretation and development of recommendations.....	29
2.5.1 Limitations to Research Methodology.....	30
2.6 Summary.....	31
Chapter 3 - Literature Review	32
3.1 Introduction.....	32

3.2	New Zealand Based Case Studies.....	32
3.2.1	Mount Adams Landslide Dam 1999.....	33
3.2.2	Mount Ruapehu Out-burst flood 2007.....	35
3.2.3	Ram Creek Landslide Dam 1981.....	36
3.2.4	Young River Landslide Dam 2007.....	38
3.3	International Based Case Studies.....	40
3.3.1	Wenchuan Earthquake, China 2008.....	40
3.3.2	Kashmir Earthquake, Pakistan 2005.....	42
3.3.3	Sunkoshi River Landslide Dam, Nepal 2014.....	43
3.3.4	Chi-Chi Earthquake, Taiwan 1999.....	44
3.4	Key Themes.....	46
3.4.1	Multi-agency response and responsibilities.....	46
3.4.2	Management and response.....	47
3.4.3	Methods of risk assessment.....	47
3.4.4	Warnings and evacuation procedures.....	48
3.4.5	Mitigation and monitoring.....	48
3.4.6	Community involvement.....	49
3.4.7	Long-term impacts.....	50
3.4.8	Future research.....	50
3.5	Summary.....	51
	Chapter 4 - Response to Landslide Dams during the Kaikoura Earthquake.....	52
4.1	Introduction.....	52
4.2	Seismic Hazard in the Region.....	52
4.3	Emergency Response to the Landslide Dams.....	54
4.3.1	Timeline of Events.....	58
4.3.2	Involvement of Organisations in Response.....	61
4.4	Summary.....	65
	Chapter 5 - Results from the Landslide Dam Response Interviews.....	66
5.1	Introduction.....	66
5.2	Roles and Responsibilities.....	67
5.2.1	Key Research Findings.....	70

5.2.2	Additional Interview Quotes	71
5.3	Communication.....	72
5.3.1	Key Research Findings.....	76
5.3.2	Additional Interview Quotes	77
5.4	Co-ordination	78
5.4.1	Key Research Findings.....	81
5.4.2	Additional Interview Quotes	82
5.5	Resources	83
5.5.1	Key Research Findings.....	87
5.5.2	Additional Interview Quotes	88
5.6	Previous Experience	89
5.6.1	Key Research Findings.....	92
5.6.2	Additional Interview Quotes	93
5.7	Community Involvement	94
5.7.1	Key Research Findings.....	96
5.7.2	Additional Interview Quotes	96
5.8	Information and Data.....	97
5.8.1	Key Research Findings.....	99
5.8.2	Additional Interview Quotes	100
5.9	Relationships.....	100
5.9.1	Key Research Findings.....	102
5.9.2	Additional Interview Quotes	102
5.10	Post-event/Long-term Management	103
5.10.1	Key Research Findings.....	106
5.10.2	Additional Interview Quotes	106
5.11	Summary	107
	Chapter 6 - Recommendations.....	108
6.1	Introduction	108
6.2	Clarify Responsibilities	109
6.3	Response Procedures.....	109
6.4	Hazard Modelling.....	111

6.5	Panel Agreement	112
6.6	Geographical Sectors Planning	113
6.7	Workshops	114
6.8	Training	115
6.9	Public Education.....	116
6.10	Resources	117
6.11	Database	118
6.12	Information Sharing	119
6.13	Summary	119
Chapter 7 - Conclusions		121
7.1	Introduction	121
7.2	Conclusions	122
7.3	Future Research	125
References.....		126
Appendix A. – Interview Questions		132
Appendix B. – Interview Information Sheet.....		137
Appendix C. – Interview Consent Form		139

List of Figures

Chapter 1

Figure 1.1 -Map showing the epicentre (red dot) at Waiiau as well as aftershocks since the 14th November 2016 (BBC News, 2016).....	4
Figure 1.2- Map showing the PGA levels recorded by GeoNet strong motion stations and the epicentre shown by the yellow star (Kaiser, et al., 2017).....	6
Figure 1.3 - Ohau Point landslides covering State Highway 1 north of Kaikoura (Petley, Kaikoura earthquake landslides: The picture slowly emerges, 2016).	9
Figure 1.4 - Landslides impacting State Highway 1 south of Kaikoura at the Paratatahi Tunnels (Dellow et al., 2017).....	9
Figure 1.5 - Leader 220 landslide dam after breaching (Petley, 2017).....	10
Figure 1.6 - Hapuku River landslide dam (GeoNet, 2016).	10
Figure 1.7 - Surface fault scarp created near Waiiau by the Kaikoura earthquake (Daly, 2016).11	
Figure 1.8 - Kekerengu Fault ruptured displacing the Bluff Station house and road by approx. 10 metres (GeoNet, n.d).	12
Figure 1.9 - Surface fault rupture map from the Kaikoura earthquake (GeoNet, 2017).	12
Figure 1.10 - Photo showing seabed rise from coastal uplift during the Kaikoura earthquake (BBC News, 2016).....	13
Figure 1.11 - An aerial shot of Kaikoura's uplifted coast and seabed (BBC News, 2016).	13
Figure 1.12 - Seaweed left high and dry by the tsunami at Oaro. Photo: D N King (GeoNet, n.d).	14
Figure 1.13 - Tsunami damage to the cottage at Little Pigeon Bay. The red area and lines are where the veranda and poles were (GeoNet, n.d).	15

Chapter 3

Figure 3.1 - Images from the GNS Science installed dam cam near the summit of Mt Ruapehu, left side shows the dam intact at 11am on 18 th March and the right side shows an hour later with a fully formed breach and water pouring through (GNS Science, 2010a).....	36
Figure 3.2 – Debris from dam-breach flood in 1981, 5km downstream of the landslide dam at Dee Creek (Nash et al., 2008).	37
Figure 3.3 - Young River landslide dam looking north west (Massey et al., n.d).....	39
Figure 3.4 – Two different mitigation techniques being demonstrated, one enlarging an overflow spillway with excavators and the other with blasting (Peng et al., 2014).....	41

Chapter 4

Figure 4.1 - Major historical earthquakes within the Kaikoura region (Rattenbury et al., 2006).	53
Figure 4.2 - Map showing Regional and District Boundaries (Local Government New Zealand, 2017).	55
Figure 4.3 - Mapped landslide dams as of 28 November 2016 (MCDEM, 2017).....	56
Figure 4.4 - Hapuku landslide dam, 17 November 2016 (BBC News, 2016).....	57
Figure 4.5 - Ote Makura River landslide dam above Goose Bay, 25 November 2016 (Telfer, 2016).	57

Chapter 5

Figure 5.1 - Warning signage on the Hapuku Bridge with upstream monitoring to stop vehicles crossing the bridge when lights flash (credit Erwin van Drunen).	104
--	-----

List of Tables

Chapter 4

Table 4.1 - Timeline of events to the response of the Kaikoura landslide dams.....	58
--	----

Chapter 5

Table 5.1 - Quotes from interviews about the roles and responsibilities in the response to the landslide dams in Kaikoura	71
Table 5.2 – Quotes from interviews about communication in the response to the landslide dams in Kaikoura.....	77
Table 5.3 – Quotes from interviews about the co-ordination in the response to the landslide dams in Kaikoura.....	82
Table 5.4 - Quotes from interviews about the resources in the response to the landslide dams in Kaikoura.	88
Table 5.5 - Quotes from interviews about the previous experience in the response to the landslide dams in Kaikoura.	93
Table 5.6 - Quotes from interviews about the community involvement in the response to the landslide dams in Kaikoura.	96
Table 5.7 - Quotes from interviews about the information and data in the response to the landslide dams in Kaikoura.	100
Table 5.8 - Quotes from interviews about the relationships in the response to the landslide dams in Kaikoura.....	102
Table 5.9 - Quotes from interviews about the long-term management in the response to the landslide dams in Kaikoura	106